




Wiring Diagram


Connectors Harting (Separated Grounds)

42 Pins. Up to 12 channel. Returns after sends.

G	-	+	G	-	+
8	8	8	1	1	1
9	9	9	2	2	2
10	10	10	3	3	3
11	11	11	4	4	4
12	12	12	5	5	5
13	13	13	6	6	6
14	14	14	7	7	7



+	-	G	+	-	G
1	1	1	8	8	8
2	2	2	9	9	9
3	3	3	10	10	10
4	4	4	11	11	11
5	5	5	12	12	12
6	6	6	13	13	13
7	7	7	14	14	14






Wiring Diagram


Connectors Harting (Separated Grounds)

72 Pins. Up to 24 channel. Returns after sends.

G	-	+	G	-	+
13	13	13	1	1	1
14	14	14	2	2	2
15	15	15	3	3	3
16	16	16	4	4	4
17	17	17	5	5	5
18	18	18	6	6	6
19	19	19	7	7	7
20	20	20	8	8	8
21	21	21	9	9	9
22	22	22	10	10	10
23	23	23	11	11	11
24	24	24	12	12	12



+	-	G	+	-	G
1	1	1	13	13	13
2	2	2	14	14	14
3	3	3	15	15	15
4	4	4	16	16	16
5	5	5	17	17	17
6	6	6	18	18	18
7	7	7	19	19	19
8	8	8	20	20	20
9	9	9	21	21	21
10	10	10	22	22	22
11	11	11	23	23	23
12	12	12	24	24	24






Wiring Diagram

Connectors Harting (Separated Grounds)

108 Pins. Up to 36 channel. Returns after sends.

G	-	+	G	-	+
19	19	19	1	1	1
20	20	20	2	2	2
21	21	21	3	3	3
22	22	22	4	4	4
23	23	23	5	5	5
24	24	24	6	6	6
25	25	25	7	7	7
26	26	26	8	8	8
27	27	27	9	9	9
28	28	28	10	10	10
29	29	29	11	11	11
30	30	30	12	12	12
31	31	31	13	13	13
32	32	32	14	14	14
33	33	33	15	15	15
34	34	34	16	16	16
35	35	35	17	17	17
36	36	36	18	18	18



+	-	G	+	-	G
1	1	1	19	19	19
2	2	2	20	20	20
3	3	3	21	21	21
4	4	4	22	22	22
5	5	5	23	23	23
6	6	6	24	24	24
7	7	7	25	25	25
8	8	8	26	26	26
9	9	9	27	27	27
10	10	10	28	28	28
11	11	11	29	29	29
12	12	12	30	30	30
13	13	13	31	31	31
14	14	14	32	32	32
15	15	15	33	33	33
16	16	16	34	34	34
17	17	17	35	35	35
18	18	18	36	36	36

