




Esquemas de Conexión

Conectores Harting (Tierras Unidas)

108 Pines. Hasta 40 Envíos 10 Retornos.

-	+	-	+	-	+
37	37	19	19	1	1
38	38	20	20	2	2
39	39	21	21	3	3
40	40	22	22	4	4
		23	23	5	5
		24	24	6	6
G	G	25	25	7	7
G	G	26	26	8	8
L1	L1	27	27	9	9
R1	R1	28	28	10	10
L2	L2	29	29	11	11
R2	R2	30	30	12	12
L3	L3	31	31	13	13
R3	R3	32	32	14	14
L4	L4	33	33	15	15
R4	R4	34	34	16	16
L5	L5	35	35	17	17
R5	R5	36	36	18	18



+	-	+	-	-	+
1	1	19	19	37	37
2	2	20	20	38	38
3	3	21	21	39	39
4	4	22	22	40	40
5	5	23	23		
6	6	24	24		
7	7	25	25	G	G
8	8	26	26	G	G
9	9	27	27	L1	L1
10	10	28	28	R1	R1
11	11	29	29	L2	L2
12	12	30	30	R2	R2
13	13	31	31	L3	L3
14	14	32	32	R3	R3
15	15	33	33	L4	L4
16	16	34	34	R4	R4
17	17	35	35	L5	L5
18	18	36	36	R5	R5

